DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D206-817 REV. D AND EARLIER
AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D206-817 REV. 2 AND EARLIER

REF. TCCA STC: SH12-3 REF. FAA STC: SR03091NY REF. EASA STC: 10039042

It has been brought to DART's attention that re-installation of the wire strike center post deflector over the D4544-1 Center Retainer (Ref. D206-817-011 kit) may result with gaps up to 0.150" between the two parts at the top and bottom.

In such cases, it is acceptable to shim gaps up to 0.150" with 2024-T3, 6061-T6, or 7075-T6 Aluminum at the top and bottom of the wire strike kit as required, and as shown in Figure 1.

Note: Apply chemical conversion coating to shim in accordance with MIL-DTL-5541 and prime per MIL-PRF-23377.




Figure 1 Shimming nose brackets for center deflector

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-O-01

APPROVED D. SHEPHERD (DE # 02)

CERT. NO .: ISSUE NO .: SH12-3

Α	NEW ISSUE			ML	13.10.03
REV.		1	DESCRIPTION	BY	DATE
DESIGN		ML	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
DRAWN		ML			
CHECKED		ASS	DRAWING NO.		REV. A
MFG. APPR.		N/A	DSI 9665		SHEET 1 OF 1
APPROVED			TITLE		SCALE
DE APPR.		#	WIRE STRIKE C		
DATE 13.10.03			COPYRIGHT @ 2013 BY DART AEROSPACE LTD.  THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLED OF THE EPPRESS CONDITION THAT IT IS  NOT TO BE USED FOR MAY PURPOSE OR COPIED OR COMMANICATED TO ANY OTHER PERSON WITHOUT  WINTTEN PERMISSION FROM DUST AEROSPACE LTD.		